SOUT ERN ROCKY MODERTAIN AREA - C' SBAD, NEW MEXICO EXPLORATION EXAMINATION REPLIT:

MAY 2 3 1977

•	
Lease or Permit No. NOO-C-14-20 5681	Land Ownership Navajo Allotted
Lessee or Permittee G. Warnock (Todilto Explorati	ion & Development Co.)
Examiner Billie E. Clark, Jr.	Date of Examination 4/22/77
Mineral & Geologic Taryestwater Canyon Member of M	Morrison Formation
Location . N2N2, Section 13, T. 13 N., R. 11	W., NMPM
Active	Inactive X
Method of Prospecting Rotary drilling	
Approved Prospecting Plan Being Followed:	Yes X No
Type of Surface Disturbance Access roads.	
Restoration of Disturbed Surface Not yet begu	in
Worked of plugging duffly below Polog ore only A	
Method of plugging drill holes: Holes are only t	temporarily plugged:
Method of drill hole cuttings disposal:	9
Number of drill holes examined: 4	Active 0
Named of order mores examined.	Abandoned ⁰
Number of drill holes completed: 71	
Number of drill holes planned for program: 104	at depth of 130 feet.
Artesian flow Type of logs run: Gamma, self-potential and resist	Yes No X
Number of core samples taken for analysis: non Located drill site area and inspected surf disturbance has taken place. Drill holes Comments: with wooden logs, which is effective.	ace disturbance; very little
Orig. to: Superintendent, Eastern Navajo Agency, B cc: Area Director, Navajo Area Office, BIA Chief, Branch of Mining Operations, USGS	

Through: Conservation Manager, Central Region, USGS

Area Mining Supervisor

L-Riles